

Spur	Hersteller	Artikelnr	Von	Bis	Baureihe	Verwaltung	Lok Nr.	Motor	H3D Umbausatz	Verwendete Motor
H0	Tillig	72021	2001	2006	BR 107	DR	107 004-4		HTI001C	1020D
H0	Tillig	72022	2002	2006	T 435	CSD	T435.0140		HTI001C	1020D
H0	Tillig	72023	2005	2006	T 435	KEG	010		HTI001C	1020D
H0	Tillig	72025	2021	2021	BR 92	Hersfelder Kreisbahn	4	220761		
H0	Tillig	72026	2022	2024	BR 92	Grube „Anna“ Alsdorf	10	220761		
H0	Tillig	72027	2022	2022	BR 92	Dampfbahn Fränkische Sch 4		220761		
H0	Tillig	72028	2025	2025	BR 92	DR	92 6494-6	220761		
H0	Tillig	72029	2026		BR 92	DRG	92 2601			
H0	Tillig	72090	2005	2009		2100 KEG	2111			
H0	Tillig	72091	2006	2006	060 DA	PTK	1547			
H0	Tillig	72092	2006	2006	060 DA	PTK	992			
H0	Tillig	72093	2006	2006	ST 43	CTL	2118			
H0	Tillig	72094	2006	2006	060 DA	PTK	1389			
H0	Tillig	72095	2007	2009	060 DA	CFR	060 801-5			
H0	Tillig	72096	2007	2007	060 DA	CFR	060 DA-1547			
H0	Tillig	72193	2007	2009	ST 43	CTL	2118			
H0	Tillig	72194	2007	2009	060 DA	PTK	1389			
H0	Tillig	72195	2007	2009	060 DA	CFR	060 801-5			
H0	Tillig	72292	2008	2008	060 DA	PTK	937			
H0	Tillig	72293	2008	2008	ST 43	CTL	2123			
H0	Tillig	72294	2008	2008	060 DA	PTK	2090			
H0	Tillig	73100	2005	2006	VT 70	DB	VT70 970	203033		
H0	Tillig	73100	2014	2020	VT 70	DB	VT70 971	203033		
H0	Tillig	73100	2014	2021	VT 70	DB	VT70 971	203033		
H0	Tillig	73101	2005	2009	VT 70	DB	VT70 939	203033		
H0	Tillig	73101	2010	2017	VT 70	DB	VT70 948	203033		
H0	Tillig	73101	2012	2018	VT 70	DB	VT70 948	203033		
H0	Tillig	73101	2015	2020	VT 70	DB	VT70 948	203033		
H0	Tillig	73101	2015	2019	VT 02	LLK	VT 02	203033		
H0	Tillig	73101	2015	2019	VT 70	DB	VT70 946	203033		
H0	Tillig	73101	2016	2016	VT 02	LLK	VT 02	203033		
H0	Tillig	73102	2004	2006	VT 135	DRG	VT135 065	203033		
H0	Tillig	73102	2015	2021	VT 135	DRG	VT135 066	203033		
H0	Tillig	73102	2015	2021	VT 135	DRG	VT135 066	203033		
H0	Tillig	73108	2005	2006	VT 172	DR	172 132-2	203033		
H0	Tillig	73110	2005	2006	BR 772	DB	772 009-7	203033		

H0	Tillig	73111	2005	2006 VT2.09	DR	VT2.09 020	202895
H0	Tillig	73123	2005	2005 BR 772	DB	772 342-2	203033
H0	Tillig	73124	2005	2009 VT 135	DR	VT135 062	203033
H0	Tillig	73124	2010	2011 VT 135	DR	VT135 109	203033
H0	Tillig	73124	2012	2019 VT 135	DR	VT135 064	203033
H0	Tillig	73124	2013	2019 VT 135	DR	186 005-5	203033
H0	Tillig	73124	2015	2020 VT 135	DR		203033
H0	Tillig	73126	2006	2009 VT 135	DRG	CvT135 068	203033
H0	Tillig	73126	2012	2017 VT 135	DRG	CvT135 122	203033
H0	Tillig	73126	2012	2018 VT 135	DRG	CvT135 122	203033
H0	Tillig	73127	2008	2011 MsBi	PKP	090008	203033
H0	Tillig	73128	2010	2012 BR 186	DR	186 258-0	203033
H0	Tillig	73129	2011	2013 M 140	CSD	M140 317	203033
H0	Tillig	73129	2015	2019 M 140	CSD	M140 312	203033
H0	Tillig	73130	2011	2013 VT 07	RTB	VT07	203033
H0	Tillig	73131	2017	2020 BR 772	LDC	772 342-1	204713
H0	Tillig	73132	2017	2020 BR 772	DB	772 141-7	204713
H0	Tillig	73133	2025	2025 BR 186	DR		203033
H0	Tillig	73140	2011	2015 VT2.09	DR	VT2.09 112	202895
H0	Tillig	73141	2012	2019 BR 171	DR	171 023-5	204713
H0	Tillig	73142	2013	2013 VT2.09	DR	VT2.09 102	202895
H0	Tillig	73144	2014	2019 BR 772	DB	772 004-8	204713
H0	Tillig	73145	2016	2016 BR 79	CFR	79 0507-8	204713
H0	Tillig	73146	2013	2020 VT2.09	DR	VT2.09 112	204713
H0	Tillig	74009	2022	2022 BR 92	DFS	4	220761
H0	Tillig	74191		VT 135	DR		203033
H0	Tillig	74192		VT 70	DB		203033
H0	Tillig	74193		CvT 135	DRG		203033
H0	Tillig	79001		CvT 135	DRG		203033
H0	Tillig	79002		VT 70	DB		203033
H0	Tillig	79003	2012	2018 BR 171	DR	171 023-5	202895
H0	Tillig	79004	2013	2018 VT2.09	DR	VT2.09 112	202895
H0	Tillig	79005	2013	2018 VT 07	RTB	VT07	203033
H0	Tillig	79006	2014	2014 VT 70	DB	70 971	203033
H0	Tillig	79007	2014	2014 VT 70	DB		203033
H0	Tillig	79008	2022	2024 BR 92		10	220761
H0	Tillig	79009	2022	2022 BR 92	DFS	4	220761

H0	Tillig	79029	2026	BR 92	DRG	92 2601		
H0	Tillig	97300	2005	2005 T 478	CSD	T478.3396		
H0	Tillig	97301	2005	2006 Rh 753	CSD	753 223-7		
H0	Tillig	97306	2005	2006 Rh 754	CSD	754 075-0		
H0	Tillig	97308	2005	2006 Rh 753	CSD	753 231-0		
H0	Tillig	97309	2005	2006 T 478	CD	T478.3001		
H0	Tillig	97310	2006	2006 Rh 753	CSD	753 001-7		
H0	Tillig	97311	2005	2006 Rh 752	FAS	D752.508		
H0	Tillig	97313	2005	2006 Rh 754	CD	754 057-8	Dummy?	
H0	Tillig	70004		BR 186 / 190	DR			203033
H0	Tillig	70008	2014	2014 VT 70	DB	VT 70 971		203033
H0	Tillig	70020	2016	2016 CvT 135	DRG			203033
H0	Tillig	70021	2015	2015 VT 02	LLK	VT 02		203033
H0	Tillig	70022	2015	2015 M 140	CSD			203033
H0	Tillig	70032		VT 70.9	DB	VT70 946		203033
H0	Tillig	70053	2024	2024 VT 135	DRG			203033
H0	Tillig	70054	2022	2022 VT 135	DR			203033
H0	Tillig	70090		VT 137	DR			203033
H0	Tillig	70091	2015	2015 VT 70.9	DB	VT70 948		203033
H0	Tillig	72012	2021	2024 BR 92	DRG	92 2602		
H0	Tillig	72013	2021	2024 TKp30	PKP	TKP30-1		220761
H0	Tillig	72014	2021	2024 040TX	SNCF	040 TX 58		220761
H0	Tillig	72016	2021	2024 BR 92	DR	92 2903		220761
H0	Tillig	72017	2021	2024 BR 92	GKA	182		220761
H0	Tillig	72018	2025	BR 92	DR	92 6492		
H0	Tillig	72020	2001	2006 V 75	DR	V75 006	HTI001C	1020D
H0	Tillig	97314	2003	2004 Rh 750	CD	750 275-0	Dummy?	
H0	Tillig	500132	2002	2002 Rh 720	CSD	720 046-2		
H0	Tillig	500560	2007	2007 060 DA	FS	DA-003		
H0	Tillig	500561	2007	2007 060 DA	FS	D361-003		
H0	Tillig	500588	2007	2007 VT 135	DFS	135 069		203033
H0	Tillig	500827	2009	2009 060 DA	CFR	60-0731-4		
H0	Tillig	501318	2014	2014 VT 135	DR	135 109		203033
H0	Tillig	501588	2016	2016 VT 02	LLK	VT 02		203033
H0	Tillig	501816	2018	2018 BR 171	DR	171 019-3		202895
H0	Tillig	501818	2018	2018 BR 171	DR	171 019-3		202895